



Notes:

- All resistors 1/2 W carbon comp UON
- All caps are uF @ 400v UON
- All DC voltages as measured.
- Original circuit was not fused.
- Original chassis was not earthed.

Suggested Improvements:

- Add fuse and grounded power cord.
- Replace all electrolytic caps.
- Solder star ground points to chassis.
- Twist filament wires.
- Replace diode.

MultiVox		
Premier 90 Reverberation		
R. Smith	Reverse Engineered 7/4/2010	S.T.A.C.