

Did you use the Fender Bassman layout for your JTM45? Could be you missed this wire? (Hence I suggested checking DC continuity with your R-meter.