


EXPORT TRANSFORMER WIRING DIAGRAM

+261_VDC
TP4

100V	230V	240V
CP4	CP6	CP6
CP2	CP7	CP7
CP8	CP2	CP8
CP6	CP8	CP2



641317
EXPORT POWER TRANSFORMER