



For C13 replacement use CE Distribution C-EC20X3-450 and strap 2 20uF sections in parallel for node A, or leave one section unused.

For C14 replacement use CE Distribution C-EC10X4-450 and strap 2 10uF sections in parallel for node C. mounting hole will need to be enlarged.

Dukane 1A385 PT

S.T.A.C.		
Dukane 1A385 PA Amp		
P. Mitcheltree	Rev 1.0a 11/20/2015	Page 1 of 1