



For C12 replacement use CE Distribution C-EC20X3-450 and strap 2 20uF sections in parallel for node A, or leave one section unused.

For C13 replacement use CE Distribution C-EC10X4-450 and strap 2 10uF sections in parallel for node C. mounting hole will need to be enlarged.

Dukane 1A385 PT