



POWER SUPPLY

POWER SUPPLY FOR RELAYS

ADD JUMPER BETWEEN POT WIPER AND .22µf CAP