

# KLD JCM25 DC Voltage test point

Test by: Standby on

Gain and Master set to minimum

Bias Adjust to -30V

Power select set to Pentode

