



1. Rev 3: Corrected tremolo circuit
2. Rev 4: Added part numbers and rectifier protection diodes.
3. Rev 5: Changed HT supply node to PI and tremolo circuits.

<b>Princeton 5881 T-0-N</b>		
A C Held	Rev 4	
	2021-10-18	